



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

October 26, 2005

CERTIFIED RETURN RECEIPT 7002 0510 0003 8603 2915

William Bown
Bonneville Quarries, Inc.
842 West 400 North
West Bountiful, Utah 84087

Subject: Five-Year Review of Reclamation Surety Estimate, Bonneville Quarries, Inc., Dove Creek Quarry (M/003/016) and Lynn Spring (M/003/025), Box Elder County, Utah

Dear Mr. Bown:

The Division conducts the periodic review of reclamation surety estimates to verify accuracy, make adjustments for escalation, and account for any site modifications that could result in a change of the surety amount presently being held for the site.

The reclamation surety for the Dove Creek and Lynn Spring quarries is due for review as of year 2004 for each of these sites. To assist us in this review, we request an updated map of your sites showing current surface facilities and disturbances. Please provide the updated maps at a scale of not less than 1 inch = 500 feet, which may include: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. These maps should include all areas which have been affected by these operations to date.


If any reclamation has been completed on the site since the last surety estimate review, complete the enclosed MR-Bond/Site-Release form. This form is also available on the Division web at www.dogm.utah.gov. Please provide a separate map of the same scale as the site map, clearly identifying these reclaimed

William Bown
Page 2 of 2
M/003/016 and M/003/025
October 26, 2005

areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Please provide this information within the next 60 days or no later than December 27, 2005. If you are unable to meet this timeframe, please contact the Division with justification for requesting additional time. Thank you for providing this information to assist us in our surety estimate review. If you have any questions concerning this letter, please contact Doug Jensen at (801) 538-5382.

Sincerely,



Susan M. White
Mine Program Coordinator
Minerals Regulatory Program

SMW:DJ:jb
Enclosure: Form MR-Bond/Site Release
cc: Doug Jensen, DOGM
Steve Flock, USFS
Mike Ford, BLM (UTU-77770 & 77028)
O:\M003-BoxElder\M0030016-DoveCreek\final\5-year-review.doc